

16 MAR 1967

LC Ship's name "ALTIS" Port Cbo. No. 6303

Last survey date 3.2.67

Class is subject to

indented shell plates J.15 and K.16 (s.s from af) being specially examined and dealt with as necessary next drydocking and to permanent repairs to bottom shell plating in way of No.2 D.B. tank (s.s) next drydocking.

S.R.L. Appendix (as ~~xxxxxxx~~ or none)

Nature of present survey (afloat and in drydock)

Docking. Damage (grounding) involving bottom plating forward as above.

Recommendation

SUBMITTED record of DS 2.67 & AS 2.67 be assigned, subject to indented shell plates J.15 and K.16 (s from a) and 'F' strake plating between frames 103/106 (p) and to bottom plating in way of No.2 D.B. tank (s) being permanently repaired next S.S. by 6.67.

DS 2.67
AS 2.67 Subject Amended.

© 2020

| | | |
|-----------|-------------|-------------|
| TO NOTE | | TRO |
| S. PLANS | S. RESEARCH | S. DEVELOP. |
| FREEBOARD | L. REPORTS | PUBS. |

S. P. H.
28/2/67

Lloyd's Register Foundation

004194-00499-0322