

M.S. ALTIS

According to the records in this Office, the following remains to complete the Continuous Survey Cycle of the machinery..... *at this date.*
It should be borne in mind that delay in completing the Survey may involve the examination of additional items.

*M/E Crankcase explosion relief devices.
Spare Gear.*

Remaining due as stated

<i>Electrical Installation</i>	<i>1.67</i>
<i>Pumping Arrgs.</i>	<i>1.67</i>
<i>G. Service Pump</i>	<i>1.67</i>
<hr/>	
<i>FW. coolers.</i>	<i>2.67</i>
<i>Ridge pump</i>	<i>3.67</i>

G
207.66



© 2020

Lloyd's Register
Foundation

004194-004199-0343