

PT

25 NOV 1965

Ship's name "ALTIS"

Port

MAN
MAN

1039
No1045

Last survey date 17.10.65.

Class is subject to

indented shell plates J.15 and K.16 (s.s. from aft)
being specially examined and dealt with as necessary
next drydocking.

S.R.L. Appendix (as ~~XXXXXX~~ none)

Nature of present survey (afloat and in drydock)

Docking.

Damage (grounding).

Temporary repairs to bottom shell plating in way of No.2
D.B. tank (s.s).

Recommendation

SUBMITTED record of DS 10,65 be assigned,
subject as above, and to permanent repairs to
bottom shell plating in way of No.2 D.B. tank
(s.s) next drydocking.

DS 10,65 subject.



© 2020

S.P.K.
10/11/65
Lloyd's Register
Foundation