

Ship's name

Port

No.

Last survey date

Class is subject to

The following items of machinery have not been
examined for more than 4 years:-

Crankcase relief devices. (6.61)

Inboard fuel valve cooling pump (5.61)

Evaporator & V's (5.61)

Windlass (5.5B)

Outboard independent air compressor. (2.60)

Inboard independent air compressor (3.61)

Both main air receivers (2.60)

5. aut. Aux. engine (4.61)

5. Inb^d Aux. engine (3.61)

Emergency Aux. O.E. (3.61)

Boys $\frac{17}{9}$
65



© 2020

Lloyd's Register
Foundation

00494-00499-0371