

COPY

LLOYD'S REGISTER OF SHIPPING



Port Palermo

15th July 1965

This is to Certify that I have surveyed part of the machinery of the M/V **ALTIS** **7.169** Gross tons of **Panagusta** for advancement of **Auxiliary Boiler Survey** whilst afloat at **Gela** on the **15th July 1965,**

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned **ABS** (with date) when the survey has been completed, subject to any condition of class being dealt with as previously recommended.

Parts now examined:—**Auxiliary Boiler Survey for record ABS (with date)** to complete the survey the upper boiler safety valves require to be adjusted under steam, and oil fuel remote control examined working.

Surveyor to Lloyd's Register of Shipping
C.M. Diviacco

KEY TO ABBREVIATIONS

| | | | | | |
|-----|--------------------------------|-----|--|--------|-----------------------------------|
| ABS | Auxiliary Boiler Survey | MBS | Main Boiler Survey | TS | Tailshaft Survey |
| CSM | Continuous Survey of Machinery | OF | Fitted for oil fuel (date) FP above 150°F. | TS(CL) | Tailshaft Survey—Continuous Liner |
| DBS | Donkey Boiler Survey | SGS | Steam Generator Survey | TSN | Tailshaft renewed |
| ES | Engine Special Survey | SPS | Steampipe Survey | TS(OG) | Tailshaft Survey—Oil Gland |

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

004194-004199-0379