

25 AUG 1954

Received from Chief Ship Surveyor

SHIP NAME "NORTHGATE" REPORT Nwc. No. 111584

standing Conditions of Class: Subject to indented bottom and side shell plating, etc. (s.s.) being permanently repaired by next Special Survey.

ACTION is DEFERRED until 5,54 for Special Survey.

Endorsement of Class (B) (As before ~~for None~~)

Surveys due: SPECIAL SURVEY (C) due 5,53.

Location of Present Survey: (Afloat and in dry dock)

Repairs on account of damage, including subject and Endorsement of Class (B) items as above: Alterations: Equipment: Special Survey.

Special Features: A new engine has been installed and the engine seating modified as approved.

Interim Certificate in order (~~Yes~~-None)

Items Outstanding: (If any for S.S. or A.S.)

S. to be completed by:

Recommendation:

SUBMITTED record of docking 5,54 and Notation of 'ss. Nwc. 7,54' be assigned, but without special conditions.

5,54 Nwc. )  
ss. Nwc. 7,54. ) Without.

~~DELETE 'ENDORSEMENT OF CLASS (B)'~~

9  
8  
54



© 2021

Lloyd's Register  
Foundation

004213-004221-0167