

COPY.

23 AUG 1944

Lloyd's Register of Shipping.



Port of HULL

21st July, 1944.

Please attach to our report No. 52508.

This is to Certify that

J. N. P. DOUGLAS,

the undersigned Surveyor to this Society did at the request of

the Owners' Representative survey the Steel Screw Steamer "HALVARD BRATT", 1030 tons gross of Gothenberg, formerly classed with the Germanischer Lloyd, on the 26th June and subsequent dates, and that the following parts of hull and machinery were examined in dry dock and afloat, viz:-

Bottom and rudder, cleaned, examined and recoated.
Propeller, sternbush and outside fastenings examined.
Holds, 'tween decks, bunkers, structure beneath
boilers, fore and aft peaks, machinery spaces,
decks, casings, ash shoots, ventilators, hatchways
and closing appliances, general equipment,
steering gear and connections and windlass.
Main and auxiliary machinery generally examined,
tried under steam and found satisfactory.
Electrical installation insulation resistance
tested and found satisfactory.
Boilers examined internally and externally; safety
valves and other mountings overhauled, found
satisfactory.
Boilers examined under steam and the safety valves
adjusted to 200 lbs. per square inch.

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have recommended that she be assigned a notation of EXAMINED L.R. 6,44, indicating that from the parts now seen, she appears to be in an efficient condition for a period of twelve months from 31st June, 1944.

It is also recommended that a record of survey 6.44 and B.S. 6,44 (200 lbs.) be made in the Register Book.

John Douglas

SURVEYOR TO LLOYD'S REGISTER.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."