

30 OCT 1958 ^{4E}

ed by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

'S NAME..... WAVE GOVERNOR..... REPORT..... Nwc..... No. 115602

CS Advanced.

MBS due 7.58, now held.

DBS due 7.58, now held.

Docking. Tailshaft seen.

The Surveyor reports the tailshaft machined in way of bush and the propeller, found wasted in way of blades, satisfactorily renewed.

IT IS SUBMITTED this vessel is eligible to remain as classed with fresh records of CS 9.58

MBS 9.58

DBS 9.58

TS (CL) 8.58.

© 2020

Lloyd's Register
Foundation

004300-004307-0017