

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYAL 9166

26th February, 1960.

Classn (S)
AH/BS

RETAIN

**WRECK
SECTION**

No 874

Dear Sirs,

Steamer "SUD"

I acknowledge receipt of your memorandum of the 18th instant, the contents of which have been noted.

This case was before the Committee at their meeting today and, in view of the fact that the Owners have relinquished the Society's class without the Overdue Surveys being carried out under the supervision of the Surveyors, instructions were given for a notation to be recorded in the Register Book indicating that the class has been expunged on account on non-compliance with the Rules.

Please inform the Owners accordingly.

Yours faithfully,

Deputy Clerk to the
Classification Committee.

WRKD R.B. 1962

The Surveyors,
BUENOS AIRES.



Lloyd's Register
Foundation

004308-004315-0138

Second Surveyor's Fee (if any)

Surveyor to Lloyd's
H. Taylor & T.O. Wint