

15 DEC 1958

Rpt. C. 11 (Contd.)

Index No. (For London Office use)

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

## ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name " EDDY BAY " Official No. 184616

Port of Registry London

This ship has been under survey at PLYMOUTH

on 14th August, 1958, and the following alterations to the conditions of assignment of loadlines have now been effected/~~made~~:—

An additional 8" Mushroom top Ventilator fitted on the Bridge Deck

above the Saloon, port side for'd.

Also an additional opening 8" x 7" has been fitted on the After Castle


bulkhead at the port side. This opening is closed by a strongly hinged

constructed mild steel Watertight flap with four toggles.

*[Signature]*

Noted  
ad  
16-12-58

A copy of this Report has been placed on board.



© 2020

Lloyd's Register Foundation

004351-004357-0198