

-2. MAY 1967

Ship's Name ~~SSMS~~ "NANCHANG" Port Auckland

Processing Number: LR 523972 Gross tons 7868 Rpt. No. 13,473

Port of Registry Liverpool Date of build 1943 Is there a Rpt. 9? No

No. of visits 3 First date 24/4/67 Last date 28/4/67

Cert. B issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) 4th 12240

Date of completing rpt. 28/4/67 Surveyed at, if different from Port above -

Safcon Cert. (ST) issued & copy herewith? No If surveyed in D.D. last date of examination -

Has a Load Line Survey been held? No Summer freeboard ~~X~~s verified -

State which additional Rpt. 8 is attached: (Cont); (A); (DR); (EQ); (Rig) -

Survey fees £15. 0. 0 Damage fee Expenses 15/Od.

S.A. fee

5-MAY 1967

M

I have surveyed the above-named ship in accordance with the Rules for Wear and Tear Repairs.

Wear and tear repairs:

Soft nose stem plating wasted and holed locally in way of 23 ft. draft mark. It was noted that the stem between the 22½ ft. and 23½ ft. draft is the only area between the 17 ft. and 29 ft. marks not previously doubled. This space now closed with a 0.60" thick doubling plate and welded.

I declare that the items detailed in this report (except as stated otherwise) comply with the requirements of the Merchant Shipping (Cargo Ship Construction and Survey) Rules 1965, applicable to this ship, and are in all respects satisfactory for the service on which the ship is intended to ply namely International voyages/voyages within the limits

(The above declaration applies only to sea-going cargo ships of 500 tons gross and above registered in the U.K.)

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. I recommend, therefore, that this ship remain as classed ~~with~~ without fresh record of ~~survey~~ survey, subject

as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

Surveyor to Lloyd's Register of Shipping  
A. Huntingford.

FRIDAY 12 MAY 1967

As now subject

FOR CHAIRMAN  
CLASSN. CTT

ALSO FOR

SPL FOR

TRO

SRL


POSTING

HEADER

CERT

ALSO FOR
SPL FOR
TRO
SRL
POSTING
HEADER
CERT

*A. Huntingford*  
Surveyor to Lloyd's Register of Shipping



004364-004368-0064

taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and action

†The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due