

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

21st October, 1963

C
DHGK/RW

Dear Sirs,

Steamer "GANESELLA"

With reference to your Report No.17914, it is concluded that a Special Survey (D) was carried out and not a Special Survey (C) as reported, and that you were in possession of the plan submitted by the Singapore Surveyors in September, 1961, showing pre Special Survey drilling thicknesses of shell and deck plating, also proposed renewals which were subsequently approved in this Office.

It is further concluded these drilling thicknesses were verified when the Special Survey was carried out at your port, and that no further significant diminution in the thicknesses found, which are considered satisfactory for four years and a notation of SS (Dr 4 years) 8.63. Confirmation on these points is desired as soon as possible.

In all future similar cases, a Report 8 (Dr) should be submitted.

Yours faithfully,

Deputy Clerk to the
Classification Committee

The Surveyors,
HONG KONG



© 2020
Lloyd's Register
Foundation

004364-004368-0190