

11 MAY 1955

Index No.

40795

(For London Office use)

## LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

SHAUKIWAN

ex

## ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name S.S. "WEMBLEY HILL"

Official No. 169729

Port of Registry London

This ship has been under survey at BIRKENHEAD.

on 4<sup>TH</sup> TO 21<sup>ST</sup> APRIL 1955 and the following alterations to the conditions ofassignment of loadlines have now been effected/~~found~~:-


Opening cut in superstructure deck forward of No 1 cargo hatchway for access to locker in No 1 Tank. Pks.

Opening protected by steel coaming 24" high 44" thick welded to deck, closed with hinged steel watertight cover 44" thick secured with toggles.

John R. Wright  
Surveyor to Lloyd's Register  
Inspected 22/4/55.

Noted  
WJ

12 MAY 1955



© 2020

Lloyd's Register  
Foundation

A copy of this Report has been placed on board.