

004369-004373-0032

GB

Ship's name "ASIA ENTERPRISES" Port Man. No. 1196

Last survey date 9.1.67

Class is subject to For conditions of class see previous endorsement.

(Rudder push of TURNOL).
(Wavy upper deck to be kept under observation).
(Main structure partly of P.403 Steel).
(Shell plate K.I. (a) buckled).

S.R.L. Appendix (as before ~~xxxxxxx~~)

Surveys due SPECIAL SURVEY (C) due 1.67 - see correspondence etc.
and Telex of 2.2.67 stating full requirements of S.S. to
be carried out on arrival Japan or ship will lose class.

Notation of 'SS(M) 9,66(4 mos)' assigned - see endorsement
dated 9.11.66.

Nature of present survey (afloat ~~xxxxxxx~~)

Wear and tear repairs including part subject items as above.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS

SS proposed to be completed ~~by~~ on ship's arrival in Japan.

Recommendation

SUBJECT to 15 fathoms of chain cable being
supplied ~~and 30 fathoms of worn chain cable~~
~~being supplied~~ and to 30 fathoms of worn chain
cable being replaced, to port and starboard
bower anchors being replaced by those of Rule
size, at the earliest opportunity, to upper
deck plates 1st inboard from stringer abreast
No.4 hatchway (p. & s) being renewed and
adjacent plating to set in shell plating (p & s)
and structure in way also buckled D.B. floors
being specially examined and dealt with as
necessary by the S.S. but without other conditions.

As Now. Subject
Without.

TO NOTE		TRO
S. PLANS	S. RESEARCH	S. DEVELOP.
FREEBOARD	E. REPORTS	PLBS.

P.T.O.

00025-0003-0005

GB

Ship's name

"ASIA ENTERPRISES" Port

Man.

No.

1196

Class is subject to

For conditions of class see previous endorsement

Last survey date 9.1.67

IN S.R.L. APPENDIX

- (Main structure partly of P.403 Steel)
- Shell plate K.1 (s a) buckled.
- (Wavy upper deck to be kept under observation).
- (Rudder bush of TUFNOL).

S.R.L. Appendix (as before xxxxxxxx)

Surveys due SPECIAL SURVEY (C) due 1.67 - see correspondence etc. and Telex of 2.2.67 stating full requirement of S.S. to be carried out on arrival Japan or ship will lose class. Notation of 'SS(M) 9,66(4 mos)' assigned see endorsement dated 9.11.66. Nature of present survey (slight xxxxxxxx) Wear and tear repairs including part subject items as above.

3/2/67

Yes/No/None

is interim certificate in order
Items outstanding if any for SS

ALL ITEMS

SS proposed to be completed on ship's arrival in Japan.

Recommendation

SUBJECT to 15 fathoms of chain cable being supplied and 30 fathoms of worn chain cable being replaced and to 30 fathoms of worn chain cable being replaced, to port and starboard power anchors being replaced by those of Rule size, at the earliest opportunity, to upper deck plates lat inboard from stringer abreast No.4 hatchway (p & s) being renewed and adjacent plating to set in shell plating (p & s) and structure in way also buckled D.B. floors being specially examined and dealt with as necessary by the S.S. but without other condition

FREEBOARD	E. REPORTS	ELDER
2 PLANS	2 RESEARCH	2 REVIEW
TO NOTE	TRO	

P.T.O.



© 2020
Lloyd's Register
Foundation