

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

2nd January, 1967.

Dear Sirs,

C.
AP/DET

S.S. "ASIA ENTERPRISES"

The Reports of Surveys carried out by the Rotterdam Surveyors during August and September have now received the consideration of the Committee.

As a result of this inspection, the ship's class has been continued subject, inter alia, to 15 fathoms of chain cable being supplied and 30 fathoms of worn chain cable being replaced at the earliest opportunity, and to the port and starboard bower anchors being replaced by those of Rule size at the earliest opportunity.

In the circumstances, I shall be glad to learn what arrangements the Owners propose to make in this respect.

Yours faithfully,

pro Classification Manager

The Surveyors,
HONG KONG.



© 2020

Lloyd's Register
Foundation

004369-004373-0063