

PT

COPY

22 NOV 1965

Ship's name "ADELPHOS PETRAKIS"

Port

KEL

No. 4051

The Notation of SS(M) 6,65 (4 mos) is assigned.

ACTION is DEFERRED for a short time for Equipment.

The class is subject to 210 fathoms of chain cable and port anchor end shackle being renewed and to 50 fathoms of chain cable being supplied at the earliest opportunity, protection for air, sounding and scupper pipes etc., in holds being fitted also to wasted bilge brackets in E.R. (p.s.f) and to No.4 D.B. tank top and internals in way being specially examined and dealt with as necessary by 10,65 and to windlass gypsy wheels and tiller being specially examined and dealt with as necessary by 10,65.

There is an S.R.L. Appendix.

Please see also letter dated 8.9.65 to Kiel Surveyors regarding proposed repairs in Rostock where no Surveyors are stationed and requesting confirmation of work done at Rostock.

The KIEL Surveyors now report 9,65 the ship examined in drydock, and subject items regarding equipment, protection of pipes in holds, wasted bilge brackets and No.4 D.B. tank top etc., dealt with. It would appear no repairs were effected in Rostock.

The windlass gypsy wheels and tiller have been specially examined and continue efficient, but Surveyors recommend these items to be kept under observation at future surveys.

Wear and tear repairs also effected.

IT IS SUBMITTED record of DS 9,65 & NOTATION SS 6,65 be assigned, subject to windlass gypsy wheels and tiller being kept under observation (9,65) but without other conditions.

DS 9,65 subject.
SS 6,65 without.

CERTIFICATE WRITTEN.

IN S.R.L. APPENDIX

Bulwark plating and stays abreast No.3 cargo hatchway (p.s.) set in Soft nose stem plating indented.

2nd deck plating in way of No.3 'tween deck wavy, max. 5/8".

IT IS FURTHER SUBMITTED the Surveyors be advised it is concluded the S.R.L. Appendix items have been examined and found satisfactory, but confirmation is desired.