

Messrs. Ailsa S.B. Co's
Yard No. 448.
"EMPIRE CRUSOE".

The Rules require that the temperature rise of dynamos is not to exceed 35°C. In this instance the Certificates of Test indicate that on the two dynamos supplied the temperature rise of one is 5°C and on the other 6°C in excess of these requirements.

IT IS SUBMITTED the Glasgow Surveyors be informed that in view of these excess temperatures the dynamos cannot be accepted.

Return test sheets

Lr 2/11



© 2020

CSW

Lloyd's Register
Foundation

2.11.45.

004369-004373-0235