

COPY.

# LLOYD'S REGISTER OF SHIPPING.

United with THE BRITISH CORPORATION REGISTER



PORT

LISBON

10th November, 1965.

P. 3075

THIS IS TO CERTIFY that

E. HARDCASTLE

the undersigned Surveyor to this Society did at the request of Messrs. REBEL-Representantes de Equipamentos Britânicos de Engenharia, Lda., Lisbon, Owners Agents, and with the consent of the Master attend on board the

s.s. "SANTA KYRIAKI" 2802 gross tons of MONROVIA

whilst afloat at Jardim do Tabaco, Lisbon, on the 23rd October 1965, for the purpose of ascertaining the nature and extent of damage stated to have been caused whilst the vessel was entering Barry Docks on the 10th October 1965 at 19.04 hours and being due to high winds and currents causing the vessel to make contact with the quay wall on the port forward side.

The damage found and listed below is considered reasonably attributable to the alleged cause.

Upon examination the following damage was found and repairs recommended without prejudice to the terms and conditions of insurance.

FOUND

Port side forward, second strake from sheer, third plate from forward set in over four frame spaces.

Plate edge above set in slightly.

Plate edge forward set in slightly.

Two frames in way of indent set in.

RECOMMENDED

Remove, fair and refit.

Fair in place.

Fair in place.

Crop, fair and refit.

The foregoing recommendations were made with a view to placing the hull of the vessel in the same good and efficient condition as before the alleged casualty occurred and all repairs have been deferred until the next dry docking.

Fee and Expenses:-

Rsc:- 860.00

*E. Hardcastle*

E. Hardcastle

Surveyor to Lloyd's Register of Shipping

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

«While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.»

(Rpt. 10)

M.T.

004369 004373-0165