

COPY

LLOYD'S REGISTER OF SHIPPING



Port C A D I Z

Date 24th. June, 1965.

This is to Certify *that I have*

surveyed the S.S. "SANTA KYRIAKI", 2802^{Gross tons}, of Monrovia, whilst she lay afloat at Malaga on the 19th. and 20th June 1965 for damage stated to have been caused by collision with M.V. "CIUDAD DE VALENCIA" off the port of Malaga on the 18th. June, 1965, and Temporary Repairs

and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating that all ^{temporary} repairs recommended by me have been completed to my satisfaction, also that I am recommending that she ~~be~~ remain as classed without fresh record of Drydocking, subject to set in sheerstrake, shell plating etc, Deck Stringer Plating etc, Bulwarks etc, being further examined and dealt with as necessary on arrival at a port in the United Kingdom.

Signed: W.N.Henckel.....

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

AS Annual Survey
BiS Biennial Survey
DS Docking Survey
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
SS(Dr) Hull Special Survey (Drilling)
SS(M) Hull Special Survey (Modified)
CSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B 80m,4,62 (MADE AND PRINTED IN ENGLAND.)

004369-004373-0275

© 2020

Lloyd's Register
Foundation