

830.

Made by

Newby Diesel

T. D. 5.

Lon.

Report No.

118523

It is submitted that ~~a copy of~~ this Report be
forwarded to the GLS. B.C. Surveyors for their
returned guidance and for completion.

Date

8.8.44

© 2020

Lloyd's Register
Foundation

6745-47

004374.004381-0245

the ship's side to be seen without lifting the platform plates. Are the overboard discharges above or below
d with a discharge valve always accessible on the plating of the vessel

E. Dep.
Have we got the B.C. left
a version?

Moore



© 2020

Lloyd's Register
Foundation