



LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

OFICINA PRINCIPAL : 71, FENCHURCH STREET, LONDRES, E.C.3

RECEIVED

- 5 SEP 1951

And... *Amend... plan* *h/3*

La correspondencia
debe dirigirse a los
Inspectores

Calle de Ibañez de Bilbao, 22,

Apartado de Correos No. 286, Bilbao

Telefono : 16139

1st September, 1951.

Dear Sir,

"CASTILLO MONTJUICH" RECLASSIFICATION

We are in receipt of your letter of the 29th ult. and note that the results of the shell drillings forwarded with our letter of the 23rd ult. have been approved.

An amended Drilling Sheet showing original lettering of the strakes and with the drillings in hundredths of an inch is forwarded as requested. An additional strake of plating is not fitted, the repairers on the plan prepared by them included the letter I and called B strake "BC". A copy of this plan showing the renewals and new stern and stem will be obtained and forwarded with our report.

The drilled plates i.e. I and J strakes (now J and H) showing deterioration were not renewed, the new plates being 17 m/m.

Yours faithfully,

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

004382-004386-0128

14

CLASSIFICATION

H

28

1

Noted Airtels copy of plan during awards

US B60 6-51

6/9/51

100-100000-100000

THE UNIVERSITY OF CHICAGO

© 2020

Lloyd's Register
Foundation