

SEL'S NAME "CASTILLO MONTJUICH"

Report

No.

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in m/m or 1/32 inch.

No. of Shell  
plates dealt with

STRAKE	AMIDSHIP				FORWARD				AFT.				Renewed		Off & On	
	Original Thick- ness.	Thickness by drilling.		Diminution if any.	Original Thick- ness.	Thickness by drilling		Diminution if any.	Original Thick- ness.	Thickness by drilling		Diminution if any.	P.	S.	REMARKS	
		Port.	Std.			port.	Std.			Port.	Std.				P.	S.
KEEL STRAKE	M	19	16	-	9	46	13	13	46	12	13		8	8	-	2
like below	L	17	17				13	13		13	13		8	10	-	-
IN SHEER STRAKE	K	15	15		50		17	13	50	13	13		11	8	-	-
Strake below	J	14	17		50		17	14	50	12	13		9	12	-	1
" "	I	15	14		50		17	14	50	10	11		10	7	-	-
" "	H	15	15		50		13	13	50	12	12		4	4	1	-
" "	G	17	17		50		17	17	50	13	14		11	12	1	1
" "	F	15	15		56		17	16	56	15	15		9	9	2	3
" "	E	17	16		72		17	17	72	15	16		11	9	3	4
" "	D	17	17		72		17	17	72	17	15		8	6	8	7
" "	BC	17	16		72		17	17	72	17	17		14	9	6	9
" "	A	16	17		72		17		72	17			14	10	1	4
" "	K	18			72				72				8		4	

Drillings at ends to be made in the vicinity of the peak bulkheads.

New F'cle side Plating 10.5 m/m.

Totals 229.

57.

004382-004386-0134

Foundation

J. S. S. S.