

Mdb No.10622

Stl. S.S. "ANDALUSIER (ex "WAR VIGOUR)

The Surveyors should be requested to ask the Builders to ascertain from the Owners whether they are agreeable to fit a Downton pump at a future date, if required to do so.



31. 3. 20



© 2020

Lloyd's Register
Foundation

004382-004386-0172