

4E

Subject to the main engine thrust collar being examined and dealt with as necessary before the end of March 1960. (12 months limit)

(first imposed 3/59)

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

19 FEB 1960

NAME..... NORMANBY HALL

REPORT Dub

No. 8825

Docking - screw shaft examined

CS advanced.

SRL item

Main engine thrust shaft collar examined at this time and considered efficient meantime. Surveyor recommends that the main engine thrust shaft collar be again examined before the end of February 1961 (12 months limit).

IT IS SUBMITTED this vessel is eligible to remain as classed with fresh record of TS (OG) 1.60 now. Subject as now recommended.



© 2021

Lloyd's Register
Foundation

18.2.60.

004387-004393-0031