

1

Sent to Chief Surveyors

GB

SHIP'S NAME

"ATHELBEACH"

Received from Chief Surveyors

REPORT

L.An,

No. 6432

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

Cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Nature of survey

Docking: Permanent repairs to damage caused by collision:

Repairs to and reinforcing of sternframe.

NOTE D.

SUBJECT to sternframe (E W. 5,58 (p.s.) and 2,60 & 10,60 (s.s.) and solepiece (reinforced 10,60) being specially examined at the next drydocking.

IN S.R.L. APPENDIX.

Indents in a few bottom and side shell plates (p & s).

C.S.S. Records Dept.
to note.



© 2021
17.1.01.
Lloyd's Register
Foundation

004387-004393-0218