

COPY

LLOYD'S REGISTER OF SHIPPING

Port LOS ANGELES HARBOUR, CALIFORNIA

October 8, 1960

This is to Certify that I have
 examined the MV "ATHELBEACH" 7533 gross tons of Liverpool, while
 vessel lay at anchor, afloat and on drydock at this Port on
 10th September, 1960 and subsequently, on account of damage
 repairs stated to have been sustained as a result of collision
 with the SS "ATLANTIC GLORY" 10th September, 1960, at the Los
 Angeles Harbour Entrance, Calif., & Stern frame & rudder repairs,
 that I will transmit to the Committee of Lloyd's Register of
 Shipping, London, a Report, stating that all repairs recommended by
 me have been completed to my satisfaction, also that I will
 recommend that she be retained as now classed with fresh record
 10/60, Subject to the stern frame (EW 5-58 Ps, EW 2-60 Ss,
 & reinforced 10-60 Ss) being specially examined at the
 vessel's next dry docking.

(Sgd) F. A. Findley

Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BIS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	SS(P)	Hull Special Survey (Progressive)

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
 the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,
 understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be
 liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register
 or publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member
 of the Surveyors, or other Officers or Agents of the Society."

15M 8-59 PRINTED IN U. S. A.

004387-004393-0230

