

Flid. 2572

4 JUL 1946

Rpt. C. 11 (Contd.)

Index No.

Lloyd's Register of Shipping.

Ship's Name S.S. "BRIGHTON" Official No. 169168

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines

in _____

RETAIN

The following alterations have now been carried out and found satisfactory:

- Gunners' temporary accomodation in after tween decks Port side now removed.
- 6 sidelights and 2 sanitary discharges in way, now removed and openings in shell plating efficiently closed by E.W. steel spigoted closing plates.

MS.

A.M.B. Edwards

SURVEYOR TO LLOYD'S REGISTER OF SHIPPING

28.6.46.

Retain for

write Note



© 2021

Lloyd's Register Foundation

004387.004393-0270

1 - 2nd Scupper and wash basin discharge fitted with double