

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

ELT

LLOYDSREG KARACHI (PAKISTAN) (16.6.66)

SAFINAEJAMHOORIYAT REURCAB VIEW AGE SHIP COMMITTEE UNABLE AGREE FURTHER
POSTPONEMENT SPECIAL SURVEY NOW DESIRED UNLESS ON ARRIVAL AMERICAN PORT
VESSEL GENERALLY EXAMINED AS FAR AS PRACTICABLE INCLUDING HOLDS TWEEN DECKS
^{SURVEYORS}
KEY PAYING PARTICULAR ATTENTION POSSIBILITY GROOVING HEELS OF FRAMES AND
WASTAGE OF BILGE SHELL PLATING AND STRUCTURE IN WAY ALSO WEATHER DECKS AND



cc FBD

© 2021

Lloyd's Register
Foundation

004405-004410-0170

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C. 3

Telephone: 20 101 0100
Telex: 100 1000

Telegraphic: Lloyd's Register, London, E.C. 3
Lloyd's Register, London, E.C. 3

HATCHWAY COAMINGS AND HULL SUBJECTS AS SRL STOP GE MACHINERY REQUIRED AND
BOILERS ALSO GENERALLY EXAMINED UNDER STEAM NOW STOP SPECIAL ATTENTION
REQUIRED LP VALVE AND ROD AT GE UNDERSTOOD BEEN REPAIRED AT PONTA DELGADA
IN MAY STOP PERIODICAL LOADLINE SURVEY REQUIRED FOR ISSUE LLST VALID UNTIL
MID SEPTEMBER 1966 STOP NEW YORK SURVEYORS ADVISED COMMITTEE

SURVEYORS

687 22



© 2021

Lloyd's Register
Foundation