


COPY

168260

LLOYD'S REGISTER OF SHIPPING

Port LiverpoolDate 7th April, 1966.

This is to Certify that ^{we} ~~I~~ have surveyed part of the machinery of the s.s. "SAFINA E JAMHOORIYAT", 6806 gross tons of Karachi for Repairs to the Starboard inboard (No.3) steam driven generator engine whilst vessel was afloat at Liverpool on 11th February, 1966, and subsequently,

and that all ^{our} ~~my~~ recommendations have been carried out to ^{our} ~~my~~ satisfaction. ^{We} ~~I~~ are reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following ~~survey records assigned~~ subject to any outstanding conditions of class being dealt with as previously recommended.

Parts now examined:—

E. Whitehouse
Surveyor to Lloyd's Register of Shipping
E. Whitehouse (for J. Bowman & self).

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150° F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or of the Surveyors, or other Officers, Servants or Agents of the Society"

004405-004410-0187