

128 SEP 1964

004405-004410-0245

Ship's name ^{SS.} SAFINA E JAMHOORIYAT

Port

Ref. # 59018, 21/8/64.

Antwerp

No. 40265

Class is subject to

None.

Last survey date 1/9/64

Repairs.

All ③ boilers superheater elements now removed. Exhaust turbine found defective (blading) & not removed as per Rotterdam & Rotterdam Surveyor recommends that the exhaust steam turbine be repaired & re-installed by 2/65 (6 mo.).

A stay late in ~~Starb.~~ boiler (leaking) made tight by E.W. and the ~~Starb.~~ Antwerp Surveyor recommends that the seal-welded stay late in Centre box of starboard boiler be renewed at next M.B.S.

C.S. Advanced.

It is submitted that this vessel is eligible to remain as **CLASSED**, subject as now recommended.

for 28/9/64

~~SPT~~ R.B. & Header to note: - Re-insulate

SPT No. 45825016 SPT.

NOTED FOR
POSTING