

1 E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Ismaïla

Rpt.

Hpl.
Hve.

No.

18096
98639

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Type of Engine

Triple Expansion & L.P. turbine
with D.R. gearing & hydraulic coupling.

If Boilers fitted with forced draught

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of

approved type

Yes
Yes
No

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + LMC 12.40.

L.P.
17/12/40.

© 2021

Lloyd's Register
Foundation

Solid Floors, thickness and spacing

41 at 302

Are Frame and Reversed Frame)

410

Bridge Deck, Angle, E or C