

Ship's name **COPTIC**  
**Appendix - B**  
Class is subject to

Port **DDN** No. **7170**  
Last survey date **15.4.65**

14 MAY 1965

- ① E.G. b/c not being used until surveyed.
- ② Port fwd. main sea inlet & stbd. ballast sea inlet valves being specially examined at next dry docking.
- ③ Repairs to entablature of stbd forward diesel generator engine being specially examined by the end of 11.65.
- ④ S.A. generator engine (M.L. repairs) to g.l. jacket being re-examined by 11.65.

Windlass clutch plate dogs sheared & new inserts welded in position. On completion windlasses examined under working conditions & found in order.

It is submitted that this vessel is eligible to remain as **CLASSED**.

subject as above.

SRL App

End. E.3

Windlass clutch plate dogs welded 4/65

© 2020

Lloyd's Register Foundation

004411-004417-0054