

Vessel's Name: SEREMBAN

Date of Build: 1945-4mo. 2165

WRECK  
SECTION

No. 973

- 2 MAY 1949

5585	Seremban (ex "Empire Seahawk")	Stl SM	142'6"   27'1"   16'0"	522	798	4 Bhd 4 WT
180428	Straits SS Co Ltd	Electric welded structure	141'0"   27'0"   18'0"	309	8' 6 1/2"	CDBf80ft95t
V S Z L	Singapore	2 Dks		486	9' 6 1/4"	PTf85t; a24t
	British	U & 2nd Stl		528		FK Mach aft
		Ct# EL				
		WirT				

RETAIN

4 Cyl 2 stroke sa	Henry Scarr Ld	Hessle	4/45	BS* (with Freeboard) 8/46
9'843" x 16'536"	BritishPolarEnginesLd	Glasgow	4/45	AS 8/46 9/48
300 SHP				MBS* 12/46 4/45 4/58/4
TS Oil Lub				nts 12/46

9/48 Singapore

PERIODICAL SURVEYS	WHEN DUE	ITEMS ALREADY HELD (IF ANY)	PORT	DATE	ITEMS REMAINING FOR COMPLETION OF SURVEY
Special Survey (Hull) Type 1	4/49	Hull Survey held, 4/49 Singapore. Awaiting confirmation of the following machinery items: Decks, 2 Ind helpe pumps, 2 aux. air compressors, Holding down bolts, star generator & engine, spare, (hand) lub oil pump, 2 GS pumps, lub oil cooler, pump & amp & steering engine exam. Hlegest test of EL winch.			
AS	4/50 4/49				
Special Survey (Machinery)	4/49				
Boiler Survey	-				
Screwshaft Survey	12/49				
Load Line Certificate Expires	12/4/50				
Annual Load Line Survey	4/49 4/50				
Refrigerating Machinery Survey (if any)	✓				

Deferred Repairs and Limits, &amp;c. (Hull)

Deferred Repairs and Limits, &amp;c. (Machinery)



© 2020

Lloyd's Register Foundation

004418-004425-0028