


"CHINA".
=====

Ham.22634.

The Surveyors should be requested to state the length and capacity of the double bottom in accordance with Circular No.1284, and the overall length in accordance with Circular No.1703.

The Surveyors should be informed it is concluded the scantlings of the after bridge are as approved and the height of the bottom transverses at sides in way of Cargo tanks is as approved, but this should be confirmed.



4.2.38.



© 2021

Lloyd's Register
Foundation