


COPY LONDON
LLOYD'S REGISTER OF SHIPPING



NEWCASTLE-ON-TYNE, No. 1896

Port. NEWCASTLE UPON TYNE.

Date 7th April, 1965.

This is to Certify *that I have surveyed part of the machinery*
of the M.S. "CAKEMORE" 4700 gross tons of Liverpool,

for Advancement of Continuous Machinery Survey, Repairs and Condition of Class, whilst afloat at Newcastle and Gateshead Quays, on the 29th March, 1965 and subsequently,

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following

survey records assigned :- C.S.M. (with date) on completion, subject to the Metalock repairs in way of No. 6 unit entablature of starboard ford. generator diesel and No. 1 unit of P(A) generator diesel being specially examined and dealt with as necessary before the end of September, 1965, and to any outstanding conditions of class being dealt with as previously recommended.

Parts now examined:—

Main Engine:— No. 6 unit cylinder, cover, piston, rod, valves and gears, connecting rod, crossheads, bearings and guides.

Auxiliaries:— Starboard ford. generator diesel metalock repair in way of No. 6 unit entablature.

Port (A) generator diesel metalock repair in way of No. 1 unit.

[Signature]
Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CSM Continuous Survey of Machinery
DBS Donkey Boiler Survey
ES Engine Special Survey

MBS Main Boiler Survey
OF Fitted for oil fuel (date) FP above 150° F.
SGS Steam Generator Survey
SPS Steampipe Survey

TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."