

"EXAMINED L.R. 2.47" (Classification Contemplated).

X LAST REPORT: 115883: LON

to Chief Surveyors

Received from Chief Surveyors

SSEL'S NAME

"OAKMORE"

Report

Liv.

No. 127091

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

PERIODICAL No. SPECIAL SURVEY PARTLY HELD.

For Classification.

When proposed to be completed

"EXAMINED 4.48" (6 mths.)

Survey held, &c., See Report.

W/D/X/P/D.

Subject to permanent repairs to tank top plating etc. in No.2 hold and to indented shell plating (p & s) and shell and deck plating etc. (fire damage) being dealt with and to indented bottom plates B.6 and 7 and C.4 and 5 (s.s.f) and A.P. bulkhead being permanently repaired at the first convenient opportunity.

not available 27/6/68

2020
Lloyd's Register
Foundation

004466-004476-0312