

Copy of supplement to Vancouver letter of 11th  
January, 1944, with First Entry Report on "FORT YUKON".

The following First Entry Hull Reports from Vancouver, B.C., should be modified so that under shall plating aft, on page 2, the bottom plating (four strakes) and bilge plating (one strake) read, in each case, .60" instead of .44".

<u>Shipbuilders</u>	<u>Hull No.</u>	<u>Ship's Name</u>	<u>Rpt. No.</u>
Burrard Dry Dock Co. Ltd.	180	"Fort Columbia"	5942
North Vancouver, B.C.	182	"Fort Bellingham"	5954
	184	"Strathcona Park"	5966
	186	"Fort St. Nicolas"	5990
	188	"For Sakisdac"	6006
	190	"Fort Machault"	6023
	192	"Beaton Park"	6046
 Burrard (Vancouver) Dry	 181	 "Fort Yukon"	 5950
Dock Co. Ltd.	183	"Wascana Park"	5956
Vancouver, B.C.	185	"Fort Massac"	5969
	187	"Fort Prudhomme"	6002
	189	"Fort Venango"	6018
	191	"Fort Orleans"	6035
	193	"Fort St. Croix"	6062
 North Van Ship Repairs Ltd.	 127	 "Fort Hall"	 5952
North Vancouver, B.C.	128	"Fort Clatsop"	5955
	129	"Fort Colville"	5970
	130	"Fort Panmure"	6001
	131	"Fort Marin"	6016
	132	"Fort Saleesh"	6023
	133	"Dundurn Park"	6045



© 2021

Lloyd's Register  
 Foundation

004677-004680-0224



©