

COPY

LLOYD'S REGISTER OF SHIPPING

COPY FOR LONDON



Port Jacksonville, Florida

Date March 15, 1965

This is to Certify that I have

surveyed the S.S. "AL HUSAINI" 7157 gross tons of Karachi on February 18th and 24th, 1966, on account of repairs to fracture port side between frames 150 and 151 immediate above deep tank top flat.

and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating that all repairs recommended by me have been completed to my satisfaction, also that I am recommending that she be retained as now classed without fresh record of survey, subject to shell plating port side in way of deep tank top flat in No. 1 hold being further examined and dealt with as found necessary and that conditions present attached to vessel's class being dealt with as previously recommended.

Knud Moller

Surveyor to Lloyd's Register of Shipping
Knud Moller

KEY TO ABBREVIATIONS

AS Annual Survey
BiS Biennial Survey
DS Docking Survey
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
SS(Dr) Hull Special Survey (Drilling)
SS(M) Hull Special Survey (Modified)
CSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or of the Surveyors, or other Officers, Servants or Agents of the Society".