

12 APR 1967

SHIP'S NAME

"BLUE MARLIN"

PORT KOB

No. 17452

APPDX

LAST SURVEY DATE 21.2.67

CLASS IS SUBJECT TO NIL

Damage to Starbd main boiler stated
caused by shortage of water.
Recommended. Subject to the Starbd
boiler being specially examined and
repairs effected as found necessary
on ship's arrival at Kaohsiung Taiwan
to which port the ship is proceeding
direct. Starbd boiler unfit for service
meantime.

It is submitted that
this vessel is eligible to
remain as CLASSED.

Subject as now recommended.

RGR
2/4/67.



© 2020

Lloyd's Register
Foundation