

yes
Sir James Clark Ross

Mdb. 14244

Report on Electric fittings.

It is submitted that, before this report receives consideration, the 'Middlesbro' surveyors be requested to fill in the particulars of conductors in the usual manner.



© 2020

27/10/30.

Library's Register
Foundation

064486-064488-0181

and is the frame effectively earthed

yes

Are the fittings as per Rule regarding: — spacing of