

110 NOV 1966

LC Ship's name "SIR JAMES CLARK ROSS" Port. Osl. No. 10549Last survey date 14.9.66Class is subject to

NONE

S.R.L. Appendix (as before ~~XXXXXX~~)

Surveys due SPECIAL SURVEY (C) due 9.65. For postponement of S.S. see letter of 30.6.65. See also letter of 19.8.66 regarding issue of certificate to proceed under her own power in ballast. FOR PROPOSED VOYAGE.

Nature of present survey (afloat and in drydock)

Docking. General Examination as above.
Wear and tear repairs.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS

SS proposed to be completed byRecommendation

SUBMITTED record of DS 9.66 be assigned
but ACTION be DEFERRED pending further information.

DS 9.66

S.R.L. APPENDIX (AMENDED)

Indented shell plates etc. (s.a) and F.6 & 7 (p.f)

SUBMITTED FOR APPROVAL.

The Surveyors state on the report the ship is proceeding to Far East Port for breaking up.

TO NOTE		TRO
S. PLANS	S. RESEARCH	S. ON OF P.T.O
FREBOARD	E. REPORTS	PUBS.

IT IS FURTHER SUBMITTED Surveyors be advised in view of the statement that the G.E. was carried out in accordance with Secretary's letter of 19.8.66 it is concluded the structure under boilers was examined but confirmation is desired.

X1411

28/10/66

17.11.66

Surveyors are
of G.E. see letter of 30.8.65. See also letter of 19.8.66
regarding issue of certificate to proceed under her own power
in ballast. G.E. Surveyors

Looking. General Examination as above.
Near and far repairs.

is interim certificate in order
these circumstances it may for

ALL ITEMS

as proposed to be completed by

Recommendation
SUMMITED record of DS 9.66 be assigned
but ACTION be DEFERRED pending further information.

DS 9.66

Indented shell plates etc. (a.a.) and E. 3 & 7 (p.1).

the surveyors state on the report the ship is proceeding to
Pan West Port for breaking up.



© 2020

Lloyd's Register
Foundation

TO NOTE	TOO
2 PLAN 14 WIND	P.T.O.
INCORPORATED	1966