

Cherbrook
38/4/52

7E

SURVEY DUE 10.52.

Ans. 9.49, 9.1195.
0.29.50 —
Ans 8/57 9.765
" 6.52, f- 2445.
~~Oct. 9.05. Fr. 80.~~
0.29.11/2

Gen^l set removed and new 6 Cyl. Diesel generator set installed 9-49.

<u>Port</u>	<u>Centre</u>	<u>Centre Ford.</u>	<u>Alt.</u>
9.50	9.50 (copy)	8.57	8.57
	6.572		6.672

The two 30. P.O.W. engines replaced by 2-70. Hiltner engs.
250 KW each 6.52 (P.O.W. set)

1 Steam
Aux. Compressors
2 on 100 Kwt airys. — then 2 replaced by 2 elec. 6-52
Starting Air { Main
Receivers { Both 6-52
2
Compr. No. 113 Aux. 9-44
Coolers P.F. + S.F. Aux. 8-57
Steam 6-52
Emergency — removed 6-52
Aux.

Injection Air Receivers	Main	None	Aux.	None

Propellers and Sea Connections	9.49.	6.82.	9.55.	Pumping Arrangements	6.82
--------------------------------	-------	-------	-------	----------------------	------

PUMPS	Bilge	h. for 2 P.R. 6.52 6.52	Piston Jan. 6.52 Jan 9.50	alt Cw. 9.50	Steering Gear	6.52
	Ballast	9.50, 6.52.			Windlass	6.52
	General Service				Evaporator	NOS. 8-57 all 9/6-52 3 Brine pumps 6-52
	Lub. Oil	Both main 6.52.			Butterworth	
	Fuel				Accriffs	© 2020

Condensing Plant	6.52	Feed Pumps (4)	Oil Burning Arrangements	6.52	Steam Pipes	6.52
Daily Service and Storage Tanks	6.52	9.49	Electric Fittings	9.49		

3m.11.48.

753 KVP.

Plan of Factory Deck Fr Bldg. in Log. Ann Rpt 17019

004488-004488-0247