

Ship's name British Birch

Port

SWS
P. Sd.

13 JUN 1963

27246

No. 7214

Last survey date 21.5.63

8.5.63

Class is subject to

new entablature being fitted to the
port air compressor steam engine by 5.63

Docking W.D 5/32"

ABS due 5/63 now held

esm advanced

SRL item above dealt with

Engine damage and temporary

repairs. Surveyor recommends

permanent repairs to the main

engine No 2 cylinder upper piston

guide be carried out by

5/64.

It is submitted that this
vessel is eligible for THE
RECORD. ABS 5/63 subject as
recommended without subject to above.



© 2020

Lloyd's Register
Foundation

12/6/63