


COPY

LONDON

C.51818

## LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER



/P.

NEWCASTLE-ON-TYNE, No 113176.

Port NEWCASTLE UPON TYNE.

23rd February, 1956.

This is to Certify that <sup>we</sup>~~I~~ haveSurveyed the <sup>Donkey</sup>~~Boiler~~ and <sup>Part</sup>~~Machinery~~ of the M.V. "HOLLYWOOD", 11447

tons gross of London, whilst afloat and in drydock at Wallsend-on-

Tyne on the 16th January, 1956 and subsequently, on account of Damage, Docking, T.S.C.L., Donkey Boiler Survey and Advancement of Machinery Survey, and that <sup>we</sup>~~I~~ have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all

recommendations made by <sup>us</sup>~~me~~ in connection therewith havebeen carried out to <sup>our</sup>~~my~~ satisfaction, and that <sup>we</sup>~~I~~ have

Recommended that the record of D.B.S. 2.56 and T.S.C.L. 2.56

now and LMC (OS) with date

be made in the Register Book in the case of this vessel when

the survey has been completed.

Parts now examined:—

Propeller, stern bush, outside fastenings, sea valves and screwshaft.

Nos. 1 and 3 cylinders, pistons, transverse beams, side rods, side and centre top end bearings, pins and guides.

No. 1 aft side and No. 4 centre bottom end bearings and pins.

Nos. 3 and 4 main bearings and journals.

Main Engine scavenge pump cylinder piston and rod and valves.

Port and Starboard Donkey Boilers (safety valves adjusted).

Engineer Surveyor to Lloyd's Register.

W. NICHOLSON, N. STEPHENSON and C. BELL.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."