

RECEIPT FOR CERTIFICATE.

Unc 42. 34716.

(Received at London Office...)

No. 2 Port of Rotterdam Date 29th April 1929.

We request that the Refrigerating Machinery and Appliances of the ~~Steam Ship~~ ^{Kulor} "Delft dijk" Year No. 318. tons No. in Register Book may be specially surveyed with a view to the notation RMC (in red) (i.e. Refrigerating Machinery Certificate) being made in the Register Book.

The vessel is to be classed in Lloyd's Register.

We hereby engage to pay the established fees, as follows, viz.:—

In the case of vessels classed in Lloyd's Register Book

	£	s.	d.		£	s.	d.
Under 80,000	-	-	-	250,000 and under 330,000 in not more than 10 compartments	24	0	0
80,000 and under 120,000	-	-	-	250,000 and under 330,000 in more than 10 compartments	-	27	0
120,000 and under 180,000 in not more than 6 compartments	15	0	0	330,000 and under 400,000 in not more than 12 compartments	30	0	0
120,000 and under 180,000 in more than 6 compartments	-	18	0	330,000 and under 400,000 in more than 12 compartments	-	36	0
180,000 and under 250,000 in not more than 8 compartments	21	0	0	Above 400,000 in not more than 14 compartments	-	36	0
180,000 and under 250,000 in more than 8 compartments	-	24	0	Above 400,000 in more than 14 compartments	-	42	0

In the case of vessels not classed in Lloyd's Register Book the fees will be double the amounts shown above.

In exceptional cases an additional charge will be made according to the service performed, and in all cases where travelling expenses are incurred by the Surveyors in connection with the above services, they are to be defrayed by the parties interested.

In no case can a record of RMC be made in the Register Book until all fees, travelling expenses, &c., due to the Society are paid.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

(Whit's Engineering and Shipway Co.)

To the Secretary,

Lloyd's Register of Shipping,

71, Fenchurch Street, London, E.C. (3)

Signature M. M. M.

Lloyd's Register
Foundation

004541-004547-0129

No. of coils in each casing

1 coil

Material of coils

steel

Can each coil be read

Robt. Aulth
14/5/29