

state for what reasons

4 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

S NAME

Cressi

REPORT

No.

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

urvey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

It is submitted that this vessel is eligible to remain as CLASSED.

subject to the screw shaft not being renewed at the next screw shaft survey, and the cylinder of the main circulating pump examined or renewed before the end of 9.52.

004579-004590-0347

arinas, guides and guideshoes, connecting rods, link motion

Lloyd's Register  
Foundation