

in the boilers, does not require pre-heating.

COPY

ELT

LLOYDS REGISTER
COPENHAGEN

(18. 1. 46.)

HENNING MAERSK YOUR REPORT 11747 COMMITTEE CONSIDERING WHETHER
MALTESE CROSS FOR HULL SHOULD BE ASSIGNED IN VIEW ACCEPTANCE
STERNFRAME AND RUDDER WITH BUREAU VERITAS CERTIFICATES PRESUMABLY
TESTED IN GERMANY FURNISH YOUR COMMENTS GIVING PARTICULARS AND
RESULTS ANY SPECIAL TESTS CARRIED OUT BY YOU

COMMITTEE

004591-004595-0034

Lloyd's Register
Foundation

cablegram of the 10th instant, the contents of which have been noted.