

Give dates and references to any letters relating to this Report

THROCOFYOSLO

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen, London

Telephone: ROYal 9166

2nd January, 1959.

Dear Sir,

Motorship "RANELLA"

assn.(S)

With reference to my letter of the 7th February last, I have to advise you that a report has been received from the Amsterdam Surveyors of a survey held in August/October when this ship was examined in drydock.

The main engine thrust block was renewed at this time and the condition of class in this respect has been deleted.

Some repairs were carried out to the main engine Nos.1 and 5 cylinder covers, but it is recommended that these covers should be again examined by the end of October, 1959. The Committee have continued the class subject to these covers receiving attention by that time.

Fresh records of Drydocking 10.58, Donkey Boiler Survey 10.58 and Screwshaft Renewal 10.58 have now been assigned.

Yours faithfully,

c.c.Osl.

pro Clerk to the
Classification Committee.

Erling Hansen Esq.,
KRISTIANSAND,
Norway.



© 2021

Lloyd's Register
Foundation

004603-004611-0046

ow ver
Index

+89

1.0
Survey