

Received from Chief Ship Surveyor 29 AUG 1956

SHIP'S NAME "BIRCHGROVE PARK" REPORT Syd. No. 29236

Existing Conditions of Class: NONE.

Alterment of Class (B) (As before or None)

Location of Present Survey: (Afloat and in dry dock)

Repairs to rudder coupling with the recommendation that the rudder mainpiece and stock be renewed by the Special Survey.

Recommendation: SUBMITTED record of docking 7,56 be assigned as recommended, subject to the rudder mainpiece and stock being renewed by 2,57.

7,56 Syd. SUBJECT

ENDORSEMENT OF CLASS (B). Indents in shell plating, etc. (p & s).



© 2020

Lloyd's Register Foundation

Handwritten signature and date: 14-8-56

004612-004620-0166

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register... to remain as classed in the Register Book without fresh record of Survey, "to remain as classed... 1,33," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."