

to R. Jessen

MEL 6 - SIMI 7586

RECEIVED

27 OCT 1952

Ansd.....

Reykjavik 23rd October 1952 .

ICELAND

Sir ,

S/T " GYLLIR "

I am in receipt of your letter of 17th instant respecting the above
1. The shell plating was drill tested while the vessel was on the slipway on
th March last , and I regret very much that this was omitted in my last report .

The following are the particulars of the results obtained :-

Strake	Amidship		Forward		Aft	
	P	S	P	S	P	S
Sheerstrake	11	15	13	11	12	12
1st below Sheer	12	11	13	12	12	12
2nd " "	12	11	14	13	14	12
3rd " "	C	11	14	C	C	C

conclude in m/m

Regarding the chain cable , I must admit that it is a mistake in my last
rt , it is as stated in my report No. 1887 , 135 F.

Secretary ,
ssn.(S)
d's Register of Shipping ,
N D O N .



Yours faithfully ,

Viggo R. Jessen
Lloyd's Register
Foundation

004621-004629-0237

CLASSIFICATION

H

A handwritten signature in dark ink, appearing to read "R. D. B." with a large, stylized flourish extending from the end.

© 2020

Lloyd's Register
Foundation